# BILTON IN AINSTY WITH BICKERTON PARISH COUNCIL

## PARISH COUNCIL ASSET RISK ASSESSMENT March 2008

### **INDEX**

Index	1	
Overview	2	
Assets Register	3	
Assets Register changes 2006-2008	4	
Asset Risk Assessments	5 - 18	
Risk Assessment Philosophy	19- 22	
<b>Asset Identification Photographs</b>	23 - 29	

#### Overview

There have been both alterations and additions to the Parish Asset Register since the last risk assessment report of 2006. These are noted on Page 5 – "Apparent changes since last report".

#### **Alterations**

With reference to the previous assessment, the most significant change is the relocation of the Parish Council Boundary Stone from its former position adjacent to the Country Boundary Marker, to the opposite (Southern) side of the road, where it is set much further back into the verge. However, whether this was done solely as a result of the recommendation or in part because of impact damage is not known.

Other alterations include refurbishment of Parish Notice Boards

#### **Additions**

The most significant additions being the provision of bridleway and field gates in Moor Lane Bilton and between Main Street Bickerton and Ingmanthorpe

#### **Recommendations**

- a) It is also noted that while the Parish Council and Village Society Notice Board appears to have been refurbished there continues to be movement in the single post supporting it which should be investigated and corrected
- b) Where control measures include periodic inspections and ad-hoc observation, these should be recorded and retained. It may be prudent to include whether any have been done as a meeting agenda item.
- c) In the context of areas of shared responsibility, (access to and the car park at the Chequers Inn) the Parish Council should ensure that they are notified of any accidents or near miss incidents which occur so that lessons can be learned and strategies to prevent reoccurrence implemented

Ashley J Watson Health & Safety Adviser 13<sup>th</sup>. March 2008